


PORCA TRAPEZOIDAL QUADRADA


- Material:** Aço 11SMnPb37 (W.NR:1.0737) – 460/650 N/mm²



Descrição		Rosca	Passo (mm)	B (mm)	L (mm)	
Rosca Direita	Rosca Esquerda					
M10	M10	10	3	25	30	0,13
M12	M12	12	3	25	30	0,12
M14	M14	14	4	30	35	0,21
M16	M16	16	4	30	35	0,20
M18	M18	18	4	35	45	0,35
M20	M20	20	4	40	50	0,51
M25	M25	25	5	45	55	0,68
M30	M30	30	6	50	60	0,88
M36	M36	36	6	60	70	0,46
M40	M40	40	7	60	70	1,35
M45	M45	45	8	65	80	1,76
M50	M50	50	8	75	90	2,73
M60	M60	60	9	85	100	3,67

PORCA TRAPEZOIDAL QUADRADA

- Material:** Latão – OT58 – 350 N/ mm²



Descrição		Rosca	Passo (mm)	B (mm)	L (mm)	
Rosca Direita	Rosca Esquerda					
M10	M10	10	3	25	30	0,14
M12	M12	12	3	25	30	0,13
M14	M14	14	4	30	35	0,23
M16	M16	16	4	30	35	0,22
M18	M18	18	4	35	45	0,38
M20	M20	20	4	40	50	0,56
M25	M25	25	5	45	55	0,74
M30	M30	30	6	50	60	0,95
M36	M36	36	6	60	70	0,91
M40	M40	40	7	60	70	1,47
M45	M45	45	8	65	80	1,92
M50	M50	50	8	75	90	2,94
M60	M60	60	9	85	100	3,95